



**NIMBUS BOATS**

## IMPORTANT MESSAGE

### Nimbus 300 R



Some Nimbus 300 R, produced from 2007 onwards, can be affected by a manufacturing defect.

The defect may cause a short circuit between earth cable on the refueling installation and charge distributor terminals, with the risk of fire as a consequence.

If you are an owner of a Nimbus 300 R, we ask you to check the boat CIN code, which is located on the transom of the hull. The hull number is identified as shown below (hull number underlined):

**SE NIMH0116H607**

The boats concerned, have hull number starting from 116 onwards.

If you own one of these boats, we ask you not to use it until a survey have been carried out and potential faults rectified. Please contact your Nimbus dealer for inspection and remedial action. Has the ownership been transferred to a new party, please revert with the new owner's contact details.

Should you have any questions, please contact Pehr Edström or Bengt Holtsén Nimbus Boats AB at; Tel. +46 31 726 77 00 or [quality@nimbus.se](mailto:quality@nimbus.se)

We thank you for your cooperation and apologize for the inconvenience we have caused.

Nimbus Boats AB  
Box 5152  
S-426 05 Västra Frölunda  
Sweden